



Fuser/Maintenance End of Life Statement

Lexmark M5155, M5163, M5170, MS810, MS811, MS812, MX710, MX711, MX810, MX811, MX812, XM5163, XM5170, XM7155, XM7163, XM7170

NOTICE:

After 40X7743/40X8420 fuser/maintenance kit has reached its End of Life (EOL), the printer will stop functioning and fusing assembly will need to be replaced. This is controlled by a function built-in to the fuser by the Original Equipment Manufacturer (OEM) to track page count.

Prior to 40X7743/40X8420 reaching its EOL, the following *80.xy* or *Scheduled Maintenance* error messages will be received via the control panel:

- 80.0x "Replace Maintenance kit"—nearly low
- 80.1x "Replace Maintenance kit"—low
- 80.2x "Replace Maintenance kit"—very low, 2000 estimated pages remain
- 80.3x "Replace Maintenance kit"—low, 0 estimated pages remain
- 80.4x "Replace Maintenance kit"—very low, 0 estimated pages remain

These messages are not indicators of a fuser error, but rather warning the customer that the fusing component is reaching or has reached its EOL. Customers receiving these errors must purchase a replacement 40X7743 fusing assembly or 40X8420 maintenance kit.

Please visit our website www.LaserPros.com or call 715-369-5995, Option 1 to order a replacement 40X7743 fusing assembly or 40X8420 maintenance kit.